

Tele: AF/7870

Ministry of Defence
Military Engineer Services
Garrison Engineer (AF) Tezpur
PO: Salonibari
Assam : 784104


2456/18-19/ 79 /E2

08 Jun 2021

Kendriya Vidyalaya No-02
Air Force Station Tezpur

SAFETY CERTIFICATE

1. Ref your letter No 1499-118/KVAFT-2/2021-22 dated 17 May 2021
2. With reference to the above subject, visual inspection has been carried out. The building as per visual inspection is safe for occupation. However the following points observed and photos attached as appendix 'A' to be attended / rectified on priority:-
 - (a) Vertical crack in Column and wall junction at Main office entry corridor (LHS).
 - (b) Horizontal Crack at GF slab & corridor wall junction observed in veranda near assembly area.
 - (c) Vertical crack in column and wall junction observed at assembly area.
 - (d) Horizontal crack at lintel and wall junction at first floor boys toilet primary wing.
 - (e) Horizontal crack at lintel level at entry gate GF boys toilet primary wing.
 - (f) Horizontal hairline through and through continuous crack observed at B wing bldgs.



(P R Prasad, IDSE)
EE (SG)
Garrison Engineer (AF)

Encl:- (as above)